Field-Power Sourcing Guide

Coordinate components, samples and export delivery around one camera or drone ground-power setup.

01

Power modules

DC-DC step-up, step-down and regulated modules. Define input, load, protection and thermal requirements.

02

Cables & connectors

Device-specific leads, locking connectors and harnesses. Confirm pinout, polarity, length and strain relief.

03

Enclosures & mounts

Coordinate CNC housings, adapter plates, cable clamps and mounts. Confirm drawings, fit and finish.

From equipment list to agreed delivery

01	**Define**	Review equipment, interfaces, loads, quantity and destination; list open specification questions.
02	**Review & quote**	Coordinate supplier options and quote the scope of parts, customization, checks, samples and freight.
03	**Sample & confirm**	Agree drawings, materials and test responsibilities. Review the sample before a follow-on order.
04	**Coordinate delivery**	Arrange agreed purchasing, inspection records, packing lists, consolidation and export shipping documents.

Prepare these details to start a review

Equipment / model: _____ Source / port: _____
Connector / cable length / drawings: _____
Quantity / destination: _____ Target timing: _____
Support needed: selection / custom parts / samples / checks / consolidated freight

Fees, minimum quantities, timing, inspection scope and available compliance documents are agreed per project. Supplier documents do not establish final-system certification. Payment and shipping terms are confirmed in the quotation. Omit sensitive or confidential material from initial inquiries.

www.extdata.cn | yuanyanghu65@gmail.com